


Shiloh Church Road Radiological Survey

Date: 12/18/19 Area: Rad Storage Area

Smear	Description	α (dpm)	β (dpm)
1	Front Floor	0	-6
2	Wall	3	-15
3	Wall	0	3
4	Middle Floor	-1	1



LEGEND: # : Smear ### : Exposure Rate (μ R/hour) - - - - - : Rad Rope



Surveyed by: [redacted]
Date: 12/18/19

Reviewed by: [redacted]
Date: 12/19/19

Comments: Exterior exposure rates collected with doors closed. All exposure rate readings collected from about 2 feet above ground. Smears were analyzed the day after collection to allow for radon decay. Rad storage conex is still posted as Radioactive Materials Areas and Airborne Radiation Area. Background at front gate reading of 10 μ R/hour.